



## Kluzná pouzdra

### Vinutá vlákna PWM





d 20 - 60 mm			
Označení	Rozměry		
	d (mm)	D (mm)	B (mm)
PWM 202420	20	24	20
PWM 202430	20	24	30
PWM 253030	25	30	30
PWM 253040	25	30	40
PWM 303620	30	36	20
PWM 303630	30	36	30
PWM 303640	30	36	40
PWM 354130	35	41	30
PWM 354140	35	41	40
PWM 354150	35	41	50
PWM 404830	40	48	30
PWM 404840	40	48	40
PWM 404860	40	48	60
PWM 455330	45	53	30
PWM 455340	45	53	40
PWM 455360	45	53	60
PWM 505840	50	58	40
PWM 505850	50	58	50
PWM 505860	50	58	60
PWM 556340	55	63	40
PWM 556350	55	63	50
PWM 556370	55	63	70
PWM 607040	60	70	40
PWM 607060	60	70	60
PWM 607080	60	70	80

**Označení:**      **PWM**                      **30**            **36**            **30**  
 P - Kluzné ložisko  
 W - Vinutá vlákna                      d            D            B  
 M - Metrická řada

## Kluzná pouzdra

### Vinutá vlákna PWM



d 65 - 110 mm			
Označení	Rozměry		
	d (mm)	D (mm)	B (mm)
PWM 657550	65	75	50
PWM 657560	65	75	60
PWM 657580	65	75	80
PWM 708050	70	80	50
PWM 708070	70	80	70
PWM 708090	70	80	90
PWM 758550	75	85	50
PWM 758570	75	85	70
PWM 758590	75	85	90
PWM 809060	80	90	60
PWM 809080	80	90	80
PWM 8090100	80	90	100
PWM 859560	85	95	60
PWM 859580	85	95	80
PWM 8595100	85	95	100
PWM 9010560	90	105	60
PWM 9010580	90	105	80
PWM 90105120	90	105	120
PWM 9511060	95	110	60
PWM 95110100	95	110	100
PWM 95110120	95	110	120
PWM 10011580	100	115	80
PWM 100115100	100	115	100
PWM 100115120	100	115	120
PWM 11012580	110	125	80
PWM 110125100	110	125	100
PWM 110125120	110	125	120

Označení: **PWM**      **70**      **80**      **90**  
 P - Kluzné ložisko  
 W - Vinutá vlákna      d      D      B  
 M - Metrická řada